

Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

**Mine Name: Claim 7
Mine ID: 81**

Navajo AUM Central Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

20074.063.017.0020

August 2011

Part I Site Identification, Location and Status**Site Names and ID numbers as applicable****Mine ID:** 81**Map ID:** C23**CERCLIS:** NNN000909182**Navajo Abandoned Mine Land Reclamation Program:** NA-0702**Local name / Aliases:** Homer Scott No. 7; Claim No. 7; Homer Scott; Claim #7; Dry Run Canyon**Chapter and local area:** Tselani / Tachee**County:** Apache **State:** Arizona**Lat/Long:** 36.2095537655 N / -109.869464914 W**Nearby road and highway:** Route 29 **Local Post Office:** Blue Gap, AZ**Surface Land Status: check one or more and provide ownership and contact information below**

Tribal Trust Land	<input checked="" type="checkbox"/>	Public lands	<input type="checkbox"/>
Private	<input type="checkbox"/>	Tribal Fee Land	<input type="checkbox"/>
Bureau of Land Mgmt	<input type="checkbox"/>	Allotment	<input type="checkbox"/>
State	<input type="checkbox"/>	Fee land	<input type="checkbox"/>

Subsurface Mineral Rights:

No information on subsurface mineral rights ownership was found in the EPA/AUM Database.

Claim and operator information:

The mine surface land status is classified as Tribal Trust Land. Historical documents identified the operator of the mine as Joseph Costanza in 1964, and Pioneer Drilling Company in 1967. No additional historical ownership / lease information was identified in the EPA / AUM database.

Number of residential structures within 200 feet of mine: None

Part II Summary of Radiological Readings

Mine ID: 81

Highest gamma radiation measurement: 196,062 counts per minute (cpm)


Background Average: 14,986 cpm **Two Times Background:** 29,972 cpm

Describe any other radiological measurements:

A total of 2,455 gamma radiation measurements were collected from the mine site, ranging from 14,356 cpm to 196,062 cpm. Measurements collected in the vicinity of the waste rock were found at a maximum level of approximately 200,000 cpm. The measurements are represented in Figures 1 and 2.

Distribution Chart and Statistics:

Site Gamma Radiation Statistics	
Number of Readings	2,455
Minimum (cpm)	14,356
Maximum (cpm)	196,062
Mean (cpm)	46,367
Median (cpm)	34,980
Standard Deviation	31,336



Part III Status of Reclamation and Mine Waste**Mine ID: 81****The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:****NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: Yes****NAMLRP Project Number: NA-0702****NAMLRP Mine features: 2 Rim Strip / Pits**

The following information was obtained from field observations collected during the 2011 site screening:**Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.****Observed reclamation work and status:****Adits:**

None observed

Waste Piles:

2 waste rock piles: Pile 1 - 300'x50', north part of site, possibly reclaimed, 300'x50', gray-brown soil; Pile 2 - 350'x250' south part of site, gray-brown soil, eastern drainage has erosion control

Pits:

None observed

Shafts:

None observed

Other Debris and Mine Features:

Drainage contains erosion control features - stone dams/walls

Part IV Site Observations and Environs

Site observations and Environs

Observed Residential Structures (number and human habitation status of structures at the following distances from mine):

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or Commercial structures (schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances from the mine):

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources (number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine):

0 to 0.25 miles: None

0.25 miles to 4 miles: Residential pond approximately 2.5 mi NW of site

Sensitive environments (all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation):

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

The Claim 7 mine claim consists of an area of 52,725.43 m². The mine was identified as being operational from 1964 to 1967. While operational, the mine had a total reported production volume of 5,614 tons. The mine surface land status is classified as Tribal Trust Land. Historical documents identified the operator of the mine as Joseph Costanza in 1964, and Pioneer Drilling Company in 1967. No additional historical ownership / lease information was identified in the EPA / AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity?

Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels?

No

Structures:

Were any structures observed within 200 feet of the mine?

No

Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine?

Yes

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Yes

Part VI Photos



Photo 1: Mine Site #81; Cliff area



Photo 2: Mine Site #81; Waste pile



Photo 3: Mine Site #81; Erosion control berms



Photo 4: Mine Site #81; Waste pile

Part VII Contacts Reports and InformationName: Eugene EsplainTitle or official role (if any): Navajo EPA Superfund ProgramTelephone number: (928) 871-7331Address: PO Box 2946, Window Rock, AZ 86515Information provided: Lead Regulatory Agency

Name: _____

Title or official role (if any): _____

Telephone number: _____

Address: _____

Information provided: _____

Name: _____


Title or official role (if any): _____

Telephone number: _____

Address: _____

Information provided: _____

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Claim 7 (81)
Tselani / Tachee Chapters, Navajo Nation



Legend

Gamma Radiation Measurements

- < 2X Background
- > 2X Background

Measured as counts per minute (cpm)

Average background 14,986 cpm

Mine Site Boundary

General Slope Direction

Observed Reclamation Feature

Observed Waste Pile

Observed Structure

Steep Grade




0 250 Feet



WESTON
SOLUTI^{ON}S


Figure 2 - Gamma Radiation Measurements
Claim 7 (81)
Tselani / Tachee Chapters, Navajo Nation



Gamma Radiation Measurements

- 0 - 10,000 cpm
- 10,000 - 25,000 cpm
- 25,000 - 50,000 cpm
- 50,000 - 100,000 cpm
- 100,000 - 250,000 cpm
- 250,000 - 500,000 cpm
- 500,000 - 1,000,000 cpm

- Mine Site Boundary
- General Slope Direction
- Observed Reclamation Feature
- Observed Waste Pile
- Observed Structure
- Steep Grade



Measured as counts per minute (cpm) Average background 14,986 cpm



WESTON
SOLUTIONS